

FIG. 1




FIG. 2





FIG. 3A

Inspection Report - Sample

Owner Information

Name: Jim Sullivan
Address: 3080 Ogden Avenue Suite 100
Minneapolis, MN 12345-9999
(419) 123-3948
jim_msullivan@msn.com



Plan Type: Dockmaster Plan
via fax @ (419) 123-4596

Dockmaster Contact

Name: Bill Watson
Phone: (630) 434-9902
Email: bwatson@yachtwatchman.com

Vessel Inspection

Vessel: The Shining Sentinel
Marina: Bay Harbor
Location: Lot 13-B
Inspected: September 14, 1999 @ 6:15 PM

- Exterior Lines

Dock Lines:	<input type="radio"/>	Checked
Anchor/Mooring:	<input type="radio"/>	<u>More Details....</u>
Dockside:	<input type="radio"/>	Checked
Connection:		

- Exterior Electric

Power Cords:	<input type="radio"/>	<u>Repair Now...</u>
Dockside:	<input type="radio"/>	Checked
Breaker:		

- Exterior Entries

Windows:	<input type="radio"/>	<u>Repaired...</u>
Doors:	<input type="radio"/>	Checked
Hatches:	<input type="radio"/>	Checked
Port Lites:	<input type="radio"/>	Checked

- Exterior Coverings

Canvas:	<input type="radio"/>	<u>More Details...</u>
---------	-----------------------	------------------------

FIG. 3B

Coverings: ☒
Bridge ☒ (N/A)
Enclosures:
Bimini Tops:

- Gound Tackle

Davits: ☒
Windlass: ☒
Boat Hooks: ☒
Cleats: ☒

- Comments

Jim, If you order repairs by the end of the week, I'll go ahead and have the boat ready for your vacation next month. I'll keep you posted with weather conditions in the area shortly before you leave. Your next scheduled inspection will be next week. - Bill